

Figure 17. Facade decay analysis of the houses on Calle del Colorado. North Facade.
Own elaboration




Figure 18. Facade decay analysis of the houses on Calle del Colorado. Soth Facade.
Own elaboration



Figure 19. Restoration intervention of the houses on Calle del Colorado. North Facade.
Own elaboration




Figure 20. Restoration intervention of the houses on Calle del Colorado. South Facade.

Own elaboration

